## JOB SAFETY ANALYSIS

## Job Description:

Change Out Drill Line While out of the Hole

Personal Protective Equipment Re Hard Hat Harness Glov	-	Fall Protection
Sequence Of Basic Job Steps:	Potential Accidents Or Hazards:	<b>Recommendations To Eliminate Or</b>
		Reduce Hazards:
1. Set truck up	Pinch points, Backing over	PPE, Beware, Walk around
2. Hang blocks	Pinch points	PPE, Beware, Keep everyone away
3. Remove drill line from Draw Works	Pinch points	PPE, Good communication
4. Pull all wraps off anchor	Pinch points	PPE, communication
<ol> <li>Run drill line through snatch Block in sub</li> </ol>	Pinch points, moving line	PPE, communication, clear work area, beware
<ol> <li>Attach snake from old drill line To new drill line</li> </ol>	Slipping, wear, hang up points	PPE, Inspect snake and connectors
7. Start spooling drill line from	Moving line, Snake slipping or	PPE, inspect snake, clear area
Draw works to other spool	breaking, pinch points	good communication
8. Tie off drill line and cut snake Off	pinch points	PPE, communication
<ol> <li>Put new drill line back on Draw works</li> </ol>	pinch points	PPE, communication
10. Put wraps back on anchor	pinch points	PPE, communication
11. Unhang blocks	pinch points, fall protection	PPE, communication