

JOB SAFETY ANALYSIS

Job Description:

String Blocks From 10 to 12 Lines

Personal Protective Equipment Required or Recommended:

Hard Hat Harness Gloves Steel Toe Boots Safety Glasses Fall Protection

Sequence Of Basic Job Steps:

Potential Accidents Or Hazards:

Recommendations To Eliminate Or Reduce Hazards:

1. Hang block	Pinch Points, Falling	PPE, Use correct tools, Good Communication
2. Remove drill line from draw works	Pinch points	PPE, Use correct tools, Good Communication
3. Remove wraps from tie down	Pinch points, Drill line slipping	PPE, Use correct tools, Good Communication
4. Attach snake	Slipping	Inspect installation and connectors
5. Unstring line from sheaves	Falling line, Hang ups, Jumping Sheaves	PPE, Keep floor clear, Good Communication
6. Tie off drill line power source,	Falling, Line falling, Pinch points	PPE, Use correct equipment, Disconnect un-stringing Good communication
7. String-up needed sheaves	Falling, Line dropping, Hang-ups	PPE, Keep floor clear, Good communication
8. Re-string sheaves	Hang ups, Snake breaking, Jumping sheaves	PPE, Keep floor clear, Good communication