

# **JOB SAFETY ANALYSIS**

**Job Description:**

String Blocks From 12 to 10 Lines

**Personal Protective Equipment Required or Recommended:**

Hard Hat

Harness

Gloves

Steel Toe Boots

Safety Glasses

Fall Protection

**Sequence Of Basic Job Steps:**

**Potential Accidents Or Hazards:**

**Recommendations To Eliminate Or Reduce Hazards:**

1. Hang block	Pinch Points, Falling	PPE, Use correct tools, Good Communication
2. Remove drill line from draw works	Pinch points	PPE, Use correct tools, Good Communication
3. Remove drill line from tie down	Pinch points, Drill line slipping	PPE, Use correct tools, Good Communication
4. Attach snake	Slipping, Hang up points	Inspect installation and connectors
5. Unstring line from sheaves	Falling line, Hang ups, Jumping Sheaves	PPE, Keep floor clear, Good Communication
6. Tie off drill line power source,	Fall hazard, Line falling, Pinch points	PPE, Use correct equipment, Disconnect un-stringing Good communication
7. Remove line from desired sheaves	Hang-ups, Jumping Sheaves, Fall Hazard	PPE, Keep floor clear, Good communication
8. Re-string Blocks	Hang ups, Snake breaking, Jumping Sheaves, Fall Hazard	PPE, Keep floor clear, Good communication