

JOB SAFETY ANALYSIS

Job Description:

Unstring Blocks

Personal Protective Equipment Required or Recommended:

Hard Hat Harness Gloves Steel Toe Boots Safety Glasses Fall Protection

Sequence Of Basic Job Steps: Eliminate Or

1. Set truck up
2. Remove drill line from draw works and tie down
3. Roll drill line up on spool derrick and spool

Potential Accidents Or Hazards:

Pinch points, Backing over
Pinch points, falling drill line
Falling drill line, pinch points

Recommendations To

Reduce Hazards:

Beware, Walk around
Use correct tools,
Keep everyone away from